	Property is: Single Fan	nily X D	uplex	Other	
Date:	11/23/2010	<u> </u>			
ake no respo	onsibility for problems discovered	after the inspe	ction da	s. The City of Milwaukee, the Redevelopment Autho te, or for omissions through error or oversight. The l deral Block Grant or HOME programs.	
Exterior	Condition Report				
ocation	Required Work	. 🗀		Note/Comments	Cost
Site	Landscaping		es	Self Help	\$ 000.00
	Steps/Handrails		es X	Rear Concrete Steps	\$ 900.00
	Service walks		es X	Rear South Side Repairs / Replace	\$ 700.00
	Fencing		es X	Repairs	\$ 400.00
	Parking	n/a X Y	es		\$
	Retaining walls	n/a χ Y	es		\$
	Other	n/a Y	es		\$
	Other	n/a Y	es		\$
Sarage	Singles: repair	n/a Y	es		\$
N/A	Shingles: Roof over existing	n/a Y	es		\$
	Shingles:Tear off & re-roof	n/a Y	es		\$
	Gutters/downspouts	n/a Y	es		\$
	Flashing	n/a Y	es 🔲		\$
	Eaves		es 🗌		\$
	Siding		es 🗌		\$
	Doors		es 🗌		\$
	Windows		es \square		\$
	Slab		es \square		\$
	Paint				\$
	Electrical		es		\$
orches	Other	n/aY	es		\$
	Roof	n/a χ Y	es 🗌		\$
	Deck-upper	n/a χ Y	es 🗌		\$
	Decklower	n/a 🗶 Y	es 🗌		\$
	Steps/handrails	n/a Y	es X	Install Rails / Repair Concrete Steps	\$ 700.00
	Ceiling	n/a χ Y	es		\$
	Guardrails	n/a χ Y	es 🗌		\$
	Structural	n/a 🗶 Y	es		\$
	Paint		es X	Complete Deck	\$ 300.00

Yes X Repair Trim Boards

n/a

Other

100.00

\$

House

Chimney	n/a 🗶 Yes 🗌		\$
Shingles: repair	n/a χ Yes 🗌		\$
Shingles: Roof over existing	n/a χ Yes 🗌		\$
Shingles:Tear off & re-roof	n/a X Yes		\$
Gutters/downspouts	n/a Yes X	Repairs	\$ 150.00
Flashing	n/a Yes X	North and South Dormers	\$ 250.00
Eaves	n/a χ Yes 🗌		\$
Siding	n/a Yes X	Repairs	\$ 200.00
Storm Doors	n/a Yes X	Front & Side Glass	\$ 300.00
Prime ("main") Doors	n/a χ Yes 🗌		\$
Storm Windows	n/a Yes X	4 Storms	\$ 400.00
Prime ("main") Windows	n/a Yes X	1 Basement Window	\$ 25.00
Paint	n/a X Yes		\$
Foundation	n/a X Yes		\$
Electrical	n/a X Yes		\$
Other	n/a Yes		\$
Other	n/a Yes		\$
Other	n/a Yes		\$
Other	n/a Yes		\$

Exterior: Estimated Cost:* \$

*average contracted cost. Actual costs may vary. Self help will reduce the amount.

4,425.00

Interior Co	ondition Report Unit: Entire unit (single family)	X		Lower unit of duplex	
Mechanical Heating	Upper unit of duplex Required Work			Other	
J	Repair/replace boiler	n/a X	Yes		\$
	Repair radiation	n/a X	Yes		\$
	Repair/replace furnace	n/a X	Yes		\$
	Repair ductwork	n/a X	Yes		\$
	Replace thermostat	n/a	Yes X	Level	\$ 0.00
	Repair/replace grilles	n/a	Yes X	Install	\$ 200.00
Electrical	Tune boiler/furn. insp ht exchange	g n/a X	Yes		\$
Liectrical	Repair/replace receptacles	n/a	Yes X	LR / 2 Bedrooms Replace	\$ 75.00
	Repair/replace switches	n/a	Yes X	LR / 2 Bedrooms Replace	\$ 75.00
	Repair/replace fixtures	n/a	Yes X	2 Fixtures	\$ 100.00
	Install outlets and circuits	n/a X	Yes		\$
	Install outlets and circuits	n/a X	Yes		\$
	Install outlets and circuits	n/a X	Yes		\$
	Install outlets and circuits	n/a X	Yes		\$
	Upgrade service	n/a X	Yes		\$
	Other	n/a	Yes		\$
	Other	n/a	Yes		\$
Plumbing	Repair/replace kitchen sink	n/a X	Yes		\$
	Repair/replace kitchen sink fauc	e n/a	Yes X	Repairs	\$ 75.00
	Repair/replace tub	n/a X	Yes		\$
	Repair/replace tub faucet	n/a	Yes X	Replace Upper Tub	\$ 75.00
	Repair/replace toilet	n/a	Yes X	Upper Toliet Replace	\$ 300.00
	Repair/replace lavatory	n/a X	Yes		\$
	Repair/replace lavatory faucet	n/a X	Yes		\$
	Repair/replace wash tub	n/a X	Yes		\$
	Repair/replace wash tub faucet	n/a X	Yes		\$
	Unclog piping:	n/a X	Yes		\$
	Repair drain/waste/vent piping	n/a	Yes X	Repairs Kitchen / 2 Baths	\$ 150.00
	Repair water piping	n/a X	Yes		\$
	Repair/replace water heater	n/a	Yes X	Replace	\$ 800.00
	Other	n/a	Yes		\$
	Other	n/a	Yes 🗌		\$

Windows						
	Replace broken glass	n/a X Yes			\$	
	Repair or replace sash	n/a X Yes			\$	
Doors		, [V] v			•	
	Repair or replace doors	n/a X Yes	Щ		\$	
	Repair or repl. locks/latches	n/a X Yes		Self Help	\$	
Walls/Ceilin	gs Repair or repl. @ defective	n/a Yes	Х	Repairs	\$	50.00
Paint	Repair or repl. @ defective	n/a Yes	X	3 Rooms	\$	150.00
	Repail of Tepl. & defective	II/a Tes	X	3 ROUTIS	Ψ	130.00
Fire Safety	Install smoke alarm:bsmt.	n/a X Yes		Self Help	\$	
	Install smoke alarm: 1st flr.	n/a X Yes		Self Help	\$	
	Install smoke alarm: 2nd flr.	n/a Yes		Self Help	\$	
Handrails	Repair/replace defective	n/a Yes	Х	Self Help Upper & Lower	\$	150.00
Stairs	Repair defective	n/a X Yes			\$	
Floors	Repair defective		X	Kitchen Floor / Upper Bath	\$	1,200.00
Other	repair derective	11/4 103		Tatorion Floor / Oppor Batti	Ψ	1,200.00
		n/a Yes			\$	
		n/a Yes			\$	
		n/a Yes			\$	
		n/a Yes			\$	
				Interior: Estimated Cost:	\$	3,400.00
				Total Exterior and Interior Cost:*	\$	7,825.00

Prepared by: S. Denny / Inspected by: Paul Geboy Date: 11/30/10

Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located on the first floor of 841 N. Broadway. If you will be occupying the home, you can get free lead-safe training from the Health Department! Call 286-5119 to schedule on-site training.

 $[\]ensuremath{^{\star}}\xspace$ average contracted cost. Actual costs may vary. Self help will reduce the amount.